



Survey No 195

Surveyed and leveled Dec 17th 1866 for Jacob Krause & Jacob Romb
 Planted a stone about 2 feet under ground in the right side
 of Sandusky River bank of C.R. & Co from center of Mill dam, Sandston
 is 14 by 17 inches flat side up and water head is witnessed by a
 driving 18 inch S 32° E 10 links Red Oak 22 inch S 84° E 26 links
 The mill dam is 51.4 feet below the level of the upper surface
 of mill stone, there is also a level mark 1.66 below mill stone
 on the south side of the Red Oak above mentioned.



Lat. No 7 as designated in the plot of the survey
 of W. S. Ragnolds made in the proceedings in part
 of the case of John Strawn or Edwin Strawn
 and others in the Court of Common Pleas of Wyand
 County Ohio containing 12 acres - being a part
 of the north east fractional quarter
 Sec. 33 T. 43 S. R. 13 E.

Surveyed Dec 18th 1866 for Richard Juntis
 at 1. Base Oak 23 in S 73° E 18 links.



Survey 197. It being that part of the NW 1/4
 of S. E. 1/4 which lies east of the Bellefontaine
 and Upper Sandusky State Road Sec 33
 T. 3. S. R. 13 E.

Surveyed preliminary Dec 19th 1866
 for Richard Juntis