


No 324.



At 1. S 1/4 Post STONE 13 Walnut 10 N 28 3/4 W 26

Beech 36 S 11 1/2 E 53

At 2. STONE Elm 10 S 66 1/2 W 59 1/2

13 Walnut 4 N 11 1/4 E 29 1/2

At 3 Stone in centre of Northern Ohio RR broken sewer pipe under stone

At 4 Centre of Sec 13 Twp 1 south Range 14 east

and stone in centre of Northern Ohio R.R.

Survey of the east half of the south west - quarter
of Section 13 township 1 south Range 14 east.

Surveyed Jan. 16th 1900 For John Truax

B. Schroyer