

SURVEY FOR - JOE HIGGINS

1" $\frac{3}{4}$ " PERSONALIZED IRON PIPE SET
PT. SW 4
SEC. 26

T. 1 S., R. 13 E.
TWP.: CRAWFORD
COUNTY: WYANDOT
OHIO.

DEED REF.: VOL. 141, PG. 401

PHYLLIS HIGGINS
141-403

FOUND $\frac{3}{4}$ " IRON PIPE UP 1'-4" &
LEANING NORTH NEXT TO
BURNED OUT POST

119.00'
S90°E

FOUND 1" IRON PIPE UP 2" &
DEFORMED ON TOP NEXT TO $8\frac{1}{2}$ "
WOODEN POST UP 6'-7"

150.00'
S0°17'30"W

PHYLLIS HIGGINS
141-403

SURVEY NO. 9102
VOL 7 PAGE 137
DATE 1-15-91

SURVEY REFERENCES:
VOL. 4, PG. 483, NO. 1137
VOL. 4, PG. 503, NO. 1156

FOUND 1" IRON PIPE UP $10\frac{1}{2}$ "
NEXT TO $8\frac{1}{2}$ "
WOODEN POST UP 6'-3"

125.00'
S90°E

FOUND 10" WOOD POST ON
CORNER UP 6'-6"; SET PIPE
2" $\pm$ NORTH OF POST

JOE HIGGINS, ETUX.
141-101
2.6783 Ac.

MARY L. VAUGHN
120-566
S4 POST SEC. 26, MON. BOX OVER IRON PIPE (SUR. REC. V. 4, PG. 481)

50°17'30"
383.486'

157.00' N90°W ASSUMED
FOUND RAILROAD SPIKE DOWN $\frac{1}{2}$ "
23.00' N90°W ASSUMED
REFERENCE

REFERENCE

N0°17'30"E
531.38'

FOUND $\frac{1}{2}$ " NAIL IN
WASHER FLUSH AT
SW CORNER OF
SEC. 26


N0°17'30"E
23.62'

N90°W
22.10.83

N90°W
244.00'

S0°17'30"W
21.514'

P.O.B.



$\frac{1}{4}$ C.H. 29 &
S. LINE SEC. 26
(40'R/W)

I Hereby Certify The Above Plot To Be True &
Correct According To A Survey.

Made on JAN. 8, 1991
Ohio Registered Surveyor No. 5647.

By Jerry B. Weininger
JERRY B. WEININGER